


# East 17th Street



## EXPLANATION

- MW-9** Groundwater Monitoring Wells Installed by MJA Consulting, Inc.
- B-11** Location and Designation of Soil Boring by MJA Consulting, Inc.
- VE-10** Location and Designation of Vapor Extraction Wells.
- AS-8** Location and Designation of Air Sparging Wells.

Note:

1. All locations are approximate. Well locations were updated 12/15/03 by survey provided by J.M. Hanks & Associates, dated October 29, 2003.
2. N.S. = Not sampled.

**(4,400)** Benzene Concentration in Groundwater in Micrograms Per Liter ( $\mu\text{g/l}$ ).

**1,000** Contour of Benzene Concentration in Micrograms Per Liter ( $\mu\text{g/l}$ ). Dashed Where Inferred.

0 25 50 75  
Approximate Graphic Scale:  
One Inch Equals 50 Feet  
North

**CJA C. JAMES & ASSOCIATES, INC.**  
Environmental Consultants

Client:  
**BEACON BAY AUTO WASH NO.3**  
OCHCA Case #90UT99  
481 East 17th Street, Costa Mesa, California

## SITE PLAN WITH BENZENE CONCENTRATIONS IN GROUNDWATER ON JANUARY 28, 2005

Plate 5

Drawn By: H.L. Approved By: H.H. Project Number: 00445 Date: January 2005